N/A presents:

Huntsville IMC Club Meeting

Topic: Un-electrified Flight Question of the Month: In the KCVO ILS-17 (See attached image), the GS (Glideslope) intercept altitude is 2800 feet at ZIKDO. The "2800" with the lightning bolt is underlined. Then the "2500" at the FAF is underlined, but it is asterisked to LOC only. Are ALL the underlined altitudes hard minimums? Let's say you either manually or on autopilot start "sliding down" the GS and happen to cross the GS intercept fix 50 feet low. It is still well within GS specs -- probably within half a dot -- but slightly below the underlined altitude. Is it legal?

EĂA/IMC Club, through the EAA's global Chapter structure, provides organized "hangar flying" focused on building instrument flying knowledge and skills. The program's network promotes a safety culture through continued education and believes that we develop safety and proficiency through education and real-life experience. Monthly meetings offer an opportunity to share inflight experiences and valuable safety tips. Through the FAA Safety Program, aviation professionals provide informative WINGS presentations. You do not have to be an instrument-rated pilot to attend. Membership in the EAA/IMC Club is encouraged but not required to participate in thismeeting. For more information

Event Details


Mon, Nov 15, 2021 - 19:00 CST Executive Flight Center

358 Bolling Road Meridianville, AL 35759



Contact: Ramona Banks 2565099329 banksrc@gmail.com

Select #: SO09108860
Representative Ramona Banks



Directions: Executive Flight Center's conference room.

A message from the National FAASTeam Manager

Earn your WINGS to get a chance to win a cash prize. Go to www.mywingsinitiative.org for more info.

Join us on Facebook: https://www.facebook.com/groups/GASafety/ Sign up for the FAA's safety services at www.FAASafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.